

1 of 1

CHAIN-OF-CUSTODY/TEST REQUEST FORM

No 4440

Project/Client Name: ARCS MR Phase 11
 Project Number: 21007 Sub 1.03
 Contact Name: Amara Vandervort
 Sampled By: Windward

Ship to: ARL
 Attn: Sue Quinn-Hood Shipping Date: 6/14/24
 Shipper: Conner Airbill Number: —
 Form filled out by: AV/CC Turnaround requested: 5d

Sample Collection Date (m/d/y)	Time	Sample Identification	Volume of Sample / # of Containers	Matrix	Test(s) Requested (check test(s) required) -						Comments / Instructions (Jar tag number(s))
					PCBs	Oil	metals	Total Sol	SUDS	Mercury	
6/13/24	1450	LOW24-SC1431H	4	Sediment	V	—	Ha	X	NA	X	
↓	1450	-SC1431J	4		X	—	Ha	X	NA	X	
6/13/24	1450	-SC1431L	4		X	—	Ha	X	NA	X	
6/14/24	0754	-SC1302A	2/3		X	—	—	X	—	X	
↓	0958	-SC1323A	4		V	—	—	X	NA	X	
↓	1342	-SC1343D	4		V	X	Ha	X	NA	X	
↓	1302	-SC1343E	4		X	X	Ha	X	NA	X	
↓	1342	-SC1343F	4		X	X	Ha	X	NA	X	
↓	1343	-SC1343G	4		X	X	Ha	X	NA	X	
6/14/24	1343	-SC1343I	4	Sediment	X	X	Ha	X	NA	X	
6/14/24											
Total Number of Containers			39	Purchase Order / Statement of Work # <u>APT US0224 ARCS ARL</u>							

1) Released by: <u>Amara Vandervort</u> Print name: <u>Amara Vandervort</u> Signature: <u>[Signature]</u> Company: <u>Windward</u> Date/Time: <u>6/14/24 16:24</u>	1) Rec'd by: <u>Oleg Lyubchenko</u> Company: <u>DL+</u> Date/Time: <u>6/14/24 16:24</u>	2) Released by: <u>[Blank]</u> Print name: <u>[Blank]</u> Signature: <u>[Blank]</u> Company: <u>[Blank]</u> Date/Time: <u>[Blank]</u>	2) Rec'd by: <u>[Blank]</u> Company: <u>[Blank]</u> Date/Time: <u>[Blank]</u>
--	---	---	---

* Distribution: White copies accompany shipment; yellow retained by consignor.



200 1st Ave W, Suite 500
 Seattle, WA 98119

206.378.1364

To be completed by Laboratory upon sample receipt:

Date of receipt::	Laboratory W.O. #:
Condition upon receipt:	Time of receipt:
Cooler temperature:	Received by: